

### ISO Tank Repair Access

#### The Problem

- Workers need to access the top of the ISO Tanks to perform maintenance and repair operations.
- The risk of a fall is high with all sides open, and potential for slipping on curved and wet surfaces at all times.

#### The Solution

- A selection of T01W with a full body harness, and extension strap provides full access from the gantry to the tank top.
- The ease of use means that the workers are more than happy to use the equipment provided, knowing that higher levels of safety have been provided.
- The rapid installation meant that the factory was only disrupted for 3 hours.

